



BALANZA DIGITAL

MP-BCD40P

Por favor, lea cuidadosamente este manual antes de usar el dispositivo por primera vez.

Guarde el manual para futuras consultas.

Lea detenidamente el presente manual de instrucciones y guárdelo para posterior consulta. En caso de entregar el aparato a terceros, entregue también el presente manual de instrucciones.

INTRODUCCIÓN

La balanza electrónica digital MAXELLPOWER MP-BCD40P es un producto de medición precisa, este producto es apto para supermercados, tiendas y otros comercios.

Esta balanza cuenta con sensores de alta precisión. Con capacidad para almacenar hasta 8 precios unitarios y 99 memorias de acumulación. Es una balanza versátil, porque también funciona con batería recargable en caso de falta de alimentación. La balanza cuenta con una función de auto apagado para ahorrar energía.

CARACTERÍSTICAS



- Especificaciones: 40kg*5g
- Precisión: 1/3000f.s
- 220v/110v y batería recargable incluida.
- Almacenamiento de 8 precios unitarios.
- Función de acumulación de pesadas (0-99)
- Función de Auto apagado para ahorrar energía.
- Pantallas:
 - Peso: 5 dígitos.
 - Precio por unidad: 5 dígitos.
 - Importe total: 6 dígitos.

DESCRIPCIÓN Y MONTAJE.

1. DESCRIPCIÓN DEL TECLADO

- ZERO: Restablece el peso a cero.
- TARE: Función para descontar el peso del recipiente.
- GRABAR (M): Se utiliza para grabar datos en la balanza.
- M+: Almacenará y acumulará los valores de peso y cantidad.
- M1-M8: 8 teclas de memoria para grabar los precios.
- C: Cancela el dato memorizado.
- 0-9: Las teclas numéricas se utilizan para la entrada del precio.
- PUNTO DECIMAL: Para introducir precios con decimales.

2. PRECAUCIÓN CON EL MONTAJE DE LA BARRA CON EL DISPLAY.




3. DESCRIPCIÓN DE LA PANTALLA

Pantallas indicadoras:

- Indicador TARE: El indicador LED está localizado bajo la pantalla Peso (Kg)
- Indicador ZERO: El indicador LED está localizado bajo la pantalla Peso (Kg)
- Indicador de encendido: El indicador LED está localizado bajo la pantalla Precio total (Kg)



4. DESCRIPCIÓN PARTE INFERIOR:



OPERAR CON LA BALANZA DIGITAL

1. INSTRUCCIONES GENERALES

- Cuando la batería se agote, conecte la balanza a la red eléctrica.
- Antes de usar la báscula compruebe que esté convenientemente nivelada. La balanza cuenta con un comprobador de nivel y patas regulables en altura para ayudar a una correcta posición.

2. OPERACIONES BÁSICAS

- Encienda la balanza mediante el botón ON/OFF, situado debajo a la derecha (ver foto apartado 'Descripción parte inferior').

3. RESTABLECER EL VALOR A CERO

Cuando no hay nada en la báscula pero la lectura no es cero, pulse la tecla ZERO para restablecer el indicador a cero.

4. PESAR

Asegúrese que los indicadores de la báscula están a cero y que la luz LED ZERO esté encendida, coloque un artículo en la bandeja, el peso se mostrará en la pantalla Peso (Weight).

5. FUNCIÓN TARA

Ponga un recipiente vacío en la bandeja (cazo, bowl, etc), una vez se muestre la lectura del peso pulse la tecla TARE, el indicador TARE se encenderá, coloque el artículo a pesar dentro del recipiente vacío. En el display aparecerá el peso real del producto descontando el peso del recipiente.

6. AVISO SOBRECARGA

En caso de sobrepasar la carga máxima, la balanza emitirá un sonido de aviso. Retire peso para evitar dañar la balanza.

7. FIJAR PRECIOS UNITARIOS

Es necesario fijar un precio para determinar el valor de los artículos pesados.

Cuando la balanza muestre el peso de del artículo, introduzca el precio mediante el teclado numérico, el precio total será mostrado en el display. Para cancelar el anterior precio unitario, presione la tecla **C**.

ACUMULACIÓN DE PESADAS

1. PREPARACIÓN

Cada vez que vaya a pesar, asegúrese de que la bandeja está vacía, que el valor acumulado está a cero, y que el lector de peso es estable y no cambia las cifras.

2. CÓMO ACUMULAR PESADAS

Ponga el artículo a pesar sobre la bandeja, espere a que el display muestre el peso, introduzca el precio, pulse la tecla M+, en el display de precio unitario aparecerá el mensaje "Add + número de pesada". Ahora, presione el botón M+, guardará los valores del peso y el precio. El monto total se irá acumulando en el display 'Importe total' (Total Price)

Ahora, retire el primer artículo de la bandeja, y repita el paso anterior. Puede usar esta función de hasta en 99 ocasiones.

3. BORRAR ACUMULACIÓN DE PESADAS

Para borrar la acumulación de pesadas presione la tecla '**C**' en cualquier momento.

4. GRABAR PRECIO UNITARIO

La balanza puede almacenar hasta 8 precios unitarios.

5. GRABACIÓN DE PRECIO UNITARIO

Presione la tecla 'M', introduzca el precio utilizando el teclado numérico.

Presione la tecla M1-M8. Este valor quedará guardado en la tecla seleccionada. Este valor puede se puede reescribir por otro.



6. CARGAR EL PRECIO UNITARIO

Si desea usar el precio unitario grabado, coloque el artículo sobre la bandeja y pulse la tecla donde se encuentre grabado el registro deseado (M1-M8), el precio unitario se mostrará junto con el peso y el importe total.

PRECAUCIONES

1. BATERÍA

- La batería debe ser debidamente recargada tras su uso sin conexión a la toma de corriente.
- El tiempo de carga normal es de 1 ó 2 horas por cada hora sin conexión a la toma de corriente.
- Si la báscula no se utiliza por un tiempo, debe cargarse continuamente, al menos, durante 24 horas. De lo contrario, podría causar dañar la batería. Antes de cargar la batería apague la báscula.

2. AGUA / TEMPERATURA

Proteja la balanza de la lluvia, inundaciones de agua, de la luz solar directa y temperaturas altas (por encima de 50 grados.) esta balanza no es resistente al agua.

3. HUMEDAD

Proteja la balanza de la humedad, no la coloque cerca de humidificadores.

4. CAMPOS MAGNÉTICOS

Proteja la balanza de campos magnéticos, podrán dañar partes delicadas de la balanza.

5. REPARACIÓN / MANTENIMIENTO

No intente abrir o reparar la balanza por sus propios medios, podría dañar la balanza permanentemente. Contacte con personal autorizado del servicio técnico para su reparación.

CONDICIONES DE GARANTÍA

- Por la presente se garantiza la calidad de este producto según plazos y condiciones de la legislación vigente.
- Quedan excluidos de esta garantía todos aquellos aparatos que presenten golpes o manipulaciones incorrectas, así como las deficiencias ocasionadas por un uso anormal o abusivo.
- La empresa, se reserva el derecho a elegir entre reparar, sustituir o canjear por otro de características similares, en función del tipo de avería o de las existencias de nuestros almacenes.
- El producto está garantizado contra todo defecto de fabricación.
- Cualquier señal de mala manipulación o mal montaje del producto por parte del cliente/usuario será motivo de anulación de garantía, teniendo que pagar el usuario la reparación.

PROBLEMAS MÁS COMUNES

PROBLEMA	INSTRUCCIÓN	CAUSA POSIBLE	REMEDIOS
Indicador de funcionamiento no se ilumina.	La báscula no está enchufada.	1) Compruebe que esté enchufada. 2) El cable está dañado.	1) Verifique que la balanza esté enchufada a una toma de red. 2) Contacte con el servicio técnico autorizado para la sustitución del cable. No intente cambiarlo vd.

<p>La balanza no se enciende con la batería</p>	<p>No hay suministro eléctrico DC en la báscula. There is no dc power supply to the scale</p>	<p>1) La batería está dañada. 2) La conexión de la batería no es correcta.</p>	<p>1) Cambie la batería por otra de iguales características. 2) Asegúrese de que la conexión de la batería es correcta.</p>
<p>El LED de sobrecarga eléctrica se enciende y la balanza se apaga automáticamente.</p>	<p>Sobrecarga eléctrica.</p>	<p>La batería ha estado en uso durante demasiado tiempo.</p>	<p>1) Cargar la batería. 2) La batería está dañada.</p>
<p>La lectura del peso cambia constantemente.</p>	<p>Sobrecarga eléctrica o excesiva humedad.</p>	<p>Voltaje insuficiente o uso de la batería demasiado prolongado incluso tras sonar la alarma. Demasiada humedad en el entorno.</p>	<p>Cargar la batería al menos 10 horas.</p>

DIGITAL SCALE

MP-BCD40P

For you safety and continued enjoyment of this product.
Always read the instruction book carefully before using

Please read these operating instructions carefully and keep them in a safe place. If you pass the unit on to someone else, please give them these operating instructions as well.

INTRODUCTION

The digital scale series Price Computing Scale is accurate measuring equipment most suitable for super markets, grocery stores and other retail outlets.

This scale is made using highly accurate and precise sensors. It is with capacity to store up to 8 unit prices and 99 accumulation memories. It is a versatile machine, because it also runs on rechargeable battery in case of lack of mains power. The scale will also automatically switched off when it is in non-use condition to save power.

FEATURES

- Specifications: 40kg*5g
- Precision:1/3000f.s
- Ac 220v/110v and build-in rechargeable battery
- Storage up to 8 unit prices
- Accumulate operation (0-99)
- Auto shut off function to save power
- Display windows:
 - Weight window: 5 digits
 - Unit price window: 5 digits
 - Total price window: 6 digits

DESCRIPTION

1. KEY DESCRIPTION

Each of the keys are shown and described for you:

- ZERO: the zero key zeroes the scale
- TARE: the tare key subtracts tare values and changes the acs from gross mode to net mode
- STORE: the store key used to store data in your scale
- ADD: add key will store and accumulate the value of weight and amount
- M1-M8: Stores unit price value at 8 different locations
- C: The c key is used for canceling the memorized data
- 0-9: the number keys are used for setting unit price data
- DECIMAL POINT: is used for setting the decimal position of unit price

2. DISPLAY DESCRIPTION


Display indicators

1. TARE indicator: the tare led is located on the left side below the weight window
2. ZERO indicator: the zero led is located on the right side below the weight window


3. AC POWER INDICATOR: ac power led is located below the total price window.



3. BOTTOM DESCRIPTION




4. CAUTIONS AND ASSEMBLY.



CAUTION ...!!

- Be very careful with the display cable when mounting the bar with the display.
- Insert the bar into the support and that the cable is in the middle without catching it between the bar and the support.
- When catching the cable, one of the wires can be broken and the scale can not work properly.
- Once the bar has been inserted in its support and the cable is well housed, it is firmly fixed with the lateral screw.
- The malfunctions of the device caused by poor assembly, broken cables and failures in the display are not covered by the warranty, as it is due to poor assembly handling by the user.



- Put the scales on a firm and level table.
- Level the scales with its level indicator so that the level bubble is completely in the center.
- To level the scale, raise or lower the feet by turning them, until the bubble is in the center.
- Repeat the leveling if you move to another table.
- A bad leveling can give failure in the heavy and the numbers may be moving continuously.

OPERATION

1. GENERAL INSTRUCTION

- When battery goes low, it is the time to charge the battery with the power line.
- Before starting, please check if the scale is in the smooth level, if not, please make adjustment.

BASIC OPERATION

1. ZERO THE SCALE

When there is nothing on the scale but reading is not zero, press the ZERO key to turn on the zero indicator.

2. WEIGHING

Ensure that scale is in zero position and zero indicator is plowing, place an item for weighing on the pan, the weight of the item will be showed on the weight window.

3. TARE

Put container on the platter, once the weight reading is stable, press the TARE key, the tare indicator will be on and the containers weight will be deducted. When it is time to clear the tare, take off the container, and press tare key again.

4. OVERLOAD WARNING

Please do not add item that is over the maximum capacity, when the scale is ringing an alarm, remove the item on the platter to avoid damage to the load cell.

5. UNIT PRICE SETTING

To trade with the scale, it is necessary to setting a unit price of the goods, then use this unit price to determine how much value of the goods which placed on the platter.

When scale displaying the weight of the goods placed on the scale, set the unit price through numeric keys, set unit price is showed in unit price window display, total price window display shows the total price of the goods. To cancel the previous unit price, press C key.

ACCUMULATOR OPERATION

1. PREPARE TO ACCUMULATE

Each time before accumulate, please make sure the platter is empty, the current accumulator values is reset to zero, and the weight reading is stable.

2. ACCUMULATION OPERATION

Put the weight item on platter, wait for the weight reading to be stable, enter the price and press the add key, the window will show "add n" being the number of how many times you press add. Now, press M+ key. Now, remove the first item from the platter, and repeat the previous step.

You can carry on this way for 99 times with the scale.

3. ACCUMULATE CLEAR

You can clear the accumulated value by press C (clear) key at any time.

4. UNIT PRICE STORAGE

The scale can store 8 sets unit price.

5. STORE THE UNIT PRICE

Press store key, then enter desired unit price using numeric keys.

Now press M*(*=1 to 8) key. The value will be stored into respective M*(*=1 to 8) key. If you have already entered any value in that key, it will be replaced by new value.



6. LOAD THE UNIT PRICE

If you want to use the unit price stored in the scale, while weighing, that press respective M*(*=1 to 8) key after the weighing display is stable, the unit price will be loaded and it will be displayed in unit price window.

CAUTION

1. BATTERY

- The battery must be recharged properly after use of the scale without mains power.
- Normally; charge for 1, 2 hours for each using 1 hour.
- If it is not used for longer time, then charge it continuously at least for 24 hours. Otherwise it will cause damage to battery.
- Before you begin to charge battery, please turn off the scale firstly.

2. WATER/TEMPERATURE

Protect your scale from heavy raining, water flooding and also from direct sunlight and high temperatures (above 50degree.) this scale is not a water proof scale.

3. HUMIDITY

Protect it from the constant humidity, don't install near humidifier.

4. MAGNETIC FIELD

Don't install your scale near strong magnetic field it may damage delicate parts of your scale.

5. REPAIR/MAINTENANCE

Don't try to open the scale by yourself or by unauthorized technical person. This may damage the scale permanently. Always contact your nearest dealer/service station for emergency repairs.

COMMON TROUBLE SHOOTING

Trouble	Instruction	Possible reason	Remedy
Ac lamp is not glowing	Power may not be connected	<ul style="list-style-type: none"> • the mains plus may be disconnected • the power cable is damaged 	<ul style="list-style-type: none"> • Insert the power plug or replace it if damaged. • Change the power cable
Scale is not turning on with battery	There is no dc power supply to the scale	<ul style="list-style-type: none"> • the storage battery is damaged • the battery 	<ul style="list-style-type: none"> • replace the battery of the similar model

		connection are not proper	<ul style="list-style-type: none"> ensure that connections are in good condition
Over voltage led glows, alarm and automatically turn off	Over voltage	Battery is in use for too long time	<ul style="list-style-type: none"> charge the battery change the battery is found damaged
Weight reading is unstable	Over voltage or affected by moisture	Insufficient voltage or use of battery is prolonged even after the warning alarm or too much humidity in surrounding	Charge the battery for at least 10 hours.

ENVIRONMENT



This appliance should not be put into the domestic garbage at the end of its durability, but must be offered at a central point for the recycling of electric and electronic domestic appliances. This symbol on the appliance, instruction manual and packaging puts your attention to this important issue. The materials used in this appliance can be recycled. By recycling of used domestic appliances you contribute an important push to the protection of our environment. Ask your local authorities for information regarding the point of recollection.

WARRANTY CONDITIONS

1. This appliance is covered against any factory defects.
2. The device is changed for a new one as long as it is within the change period and is returned with all accessories and packaging in good condition.
3. The guarantee will be valid as long as the appliance is accompanied by your invoice or purchase ticket where the exact device and model, or your warranty card duly completed and sealed, is reflected.
4. The appliance will be exempt from warranty when:
 - The appliance has signs of knocks and / or falls.
 - The appliance shows signs of misuse.
 - The appliance has signs of overuse.
 - The appliance is improperly handled.
 - No supporting document. (Card, ticket or invoice).
 - The appliance has not been used in accordance with the instructions for use.

NOTE:

Under no circumstances will direct change or direct payment be made without first reviewing the device and the causes for which it has fai



